

FIG. 2

Step 22 :  $\uparrow \uparrow (R1, P, R0)$   
 $D_1$




FIG. 3(a)

Step 23 :  $\uparrow \uparrow (R1, P, R0)$   
 $D_1$







FIG. 3(b)






FIG. 3(f)




FIG. 3(g)




FIG. 4(a)




FIG. 4(b)




FIG. 4(c)




FIG. 4(d)




FIG. 4(e)




FIG. 4(f)




FIG. 4(g)




FIG. 4(h)




FIG. 4(i)




FIG. 5(a)




FIG. 5(b)




FIG. 5(c)




FIG. 5(d)




FIG. 5(e)




FIG. 5(f)




FIG. 5(g)




FIG. 5(h)




FIG. 5(i)




FIG. 6(a)

FIG. 6(b)

FIG. 6(c)

FIG. 6(d)

FIG. 6(e)




FIG. 6(f)




FIG. 6(g)




FIG. 6(h)




FIG. 6(i)






FIG. 7(a)

FIG. 7(b)

FIG. 7(c)

FIG. 7(d)

FIG. 7(e)




FIG. 7(f)

FIG. 7(g)

FIG. 7(h)

FIG. 7(i)




FIG. 8(a)




FIG. 8(b)




FIG. 8(c)




FIG. 8(d)




FIG. 8(e)




FIG. 8(f)




FIG. 8(g)




FIG. 8(h)




FIG. 8(i)

erasing

1	1	1	1
1	1	1	1
1	1	1	1
1	1	1	1

FIG. 9(a)

$\hat{\uparrow}(R1, P, R0)$   
 $\downarrow_{D_1}$

$\times$		$\uparrow$	$\uparrow$
	$\times$	$\uparrow$	$\uparrow$
		$\times$	$\uparrow$
			$\times$

FIG. 9(b)

$\hat{\uparrow}(R1, P, R0)$   
 $\downarrow_{D_1}$

			$\uparrow$
		$\uparrow$	$\uparrow$
	$\uparrow$	$\uparrow$	$\uparrow$
$\uparrow$	$\uparrow$	$\uparrow$	$\uparrow$

FIG. 9(c)

$\hat{\uparrow}(R0)$   
 $\downarrow_{D_1}$

$\times$	$\uparrow$	$\uparrow$	$\uparrow$
	$\times$	$\uparrow$	$\uparrow$
		$\times$	$\uparrow$
			$\times$

FIG. 9(d)

erasing

1	1	1	1
1	1	1	1
1	1	1	1
1	1	1	1

FIG. 9(e)

$\downarrow(R1, P, R0)$   
 $\downarrow_{D_1}$

			$\downarrow$
	$\downarrow$	$\downarrow$	$\downarrow$
		$\times$	$\downarrow$
			$\times$

FIG. 9(f)

$\downarrow(R1, P, R0)$   
 $\downarrow_{D_1}$

$\times$	$\downarrow$	$\downarrow$	$\downarrow$
	$\times$	$\downarrow$	$\downarrow$
		$\times$	$\downarrow$
			$\times$

FIG. 9(g)

$\hat{\uparrow}(R0)$   
 $\downarrow_{D_1}$

			$\uparrow$
		$\uparrow$	$\uparrow$
	$\uparrow$	$\uparrow$	$\uparrow$
$\uparrow$	$\uparrow$	$\uparrow$	$\uparrow$

FIG. 9(h)




FIG. 10(a)




FIG. 10(b)




FIG. 10(c)




FIG. 10(d)




FIG. 10(e)




FIG. 10(f)




FIG. 10(g)




FIG. 10(h)

erasing




FIG. 11(a)

$\Downarrow_{D_1}(R1, P, R0)$




FIG. 11(b)

$\Downarrow_{D_1}(R1, P, R0)$




FIG. 11(c)

erasing




FIG. 11(d)

$\Uparrow_{D_1}(R1, P, R0)$




FIG. 11(e)

$\Uparrow_{D_1}(R1, P, R0)$




FIG. 11(f)

$\Uparrow_{D_1}(R0)$




FIG. 11(g)

$\Downarrow_{D_2}(P)$




FIG. 11(h)

$\Uparrow_{D_1}(R0)$




FIG. 11(i)